Fire Risk Assessment

Premises: Livingston Tower, 26-30 Richmond Street, Glasgow G1 1XH

Assessor: R. McCheyne

Completed on: 14th February 2011

Safety Services Room 8.20 Graham Hills Building 50 George Street Glasgow G1 1QE 0141 548 2726 <u>safety@strath.ac.uk</u>





Introduction

This Fire Risk Assessment report has been produced following an inspection of the above premises, and is intended to satisfy the requirements of The Fire (Scotland) Act 2005.

This fire risk assessment supersedes all previously issued fire safety reports, certificates and any fire risk assessment issued prior to the date of this document.

The premises have been visited and discussions have taken place with those persons having control over the premises.

This risk assessment must be kept under regular review, actions taken as identified within the assessment and reviewed where changes to operational procedures, events, or material alterations to the building arise then this risk assessment will require reviewing and updating before, during, and after such occasions to ensure that all the fire precautions in your premises remain current and adequate. It should be reviewed at least annually.

A copy of this risk assessment must be held on the premises for auditing, review and inspection by the appropriate local authority fire & rescue service enforcement office.

Further information relating to the fire safety requirements specific to these premises can be obtained from The Fire (Scotland) Act 2005, the supporting Fire Safety (Scotland) Regulations 2006 and from http://www.infoscotland.com/firelaw

Livingston Tower, 26-30 Richmond Street, Glasgow G1 1XH

BUILDING / DEPARTMENT

Various Occupiers @ January 2011 (See List)

MODERATE RISK THE OVERALL FIRE RISK RELATING TO THE PREMISES IS **USE OF PREMISES** (Place X in boxes as applicable) Offices Conference Storerooms Plant rooms Educational **Teaching facilities Computer Facilities** rooms Х Х Х Х Х Х Х

DETAILED DISCRIPTION OF THE PREMISES

Type of construction, number of buildings, number of storeys, location etc.

This is a fifteen storey building (with plant room above on flat roof) originally designed, engineered and purpose built as a hotel and offices circa early 1960's. It comprises of a reinforced concrete framed building with exterior metal framed glazed infill panels and glazed metal window openings which provide natural light to the interior of the building. There is a central core area of the building housing passenger lifts and 2 stairways serving all upper floors. The main entrance is off Richmond St and is above an open sided car park and retail units fronting George Street of this steep sloping site; (See photo below). The topmost roof level is of a flat construction having limited access to plant and lift motor room. An additional storey has been added to the topmost roof level. It has approximately 12600m² of internal floor area. Constructed to comply with The Building (Scotland) Act 1959 and subsequent amendments to the building Regulations.



An external view of the building from Rottenrow Gardens & George Street.

It is noted that the building sits above a partially enclosed two storey car park and a row of retail units fronting George Street. Although these form an integral part of the building, they are physically separated by substantial fire resisting floors and columns between the topmost car park and floors above. However, the East means of escape stairway enclosure does pass above the upper underlying car park; egressing down and into the adjoining North Portland Street. This lower level route also serves the car park. The lowest level car park and the shops do not form part of this Fire Risk Assessment, as these are operated and managed by independent operators. The car park accessed from

Fire Risk Assessment 2010 Page 3 of 30

Richmond Street is part owned and operated by the University. However the area directly underneath the Tower is currently not in use and is fenced off. The building has undergone several alterations to the internal layout since its initial construction. Teaching facilities and departmental offices are located throughout all levels of the building. The campus security control room and office facilities are located at the Richmond Street entrance of the building. Internally, reinforced concrete, steel, light weight block-work, timber, metal stud partition, plasterboard, plaster finished surfaces and vermiculite ceiling tiles are used. The outer walls have a large percentage of glazing to all sides of the building. The roof is of flat construction with a bitumen outer skin. Separating floors are of re-enforced concrete slab construction.

The building stands on a steep sloping site and there are two principal exit stairs serving the upper levels to allow egress from the building. Both stairs exit at the main entrance / street level allowing egress onto Richmond Street & North Portland Street.

Access to plant & machinery, part located on the roof and throughout the building within plant rooms, service risers and corridors; is limited to estates services staff and plant engineers on an issued "permit to work".

Overall there are two main escape stairs serving all the upper levels, both exiting onto Richmond Street & North Portland Street.

Push button key-code operated door locking devices are in operation throughout various departments and areas of the building, however where these form part of the means of escape, these appear to release either on the actuation of the fire alarm and detection system or have a manual lever on the exit route side (way out) to override the lock.

The fire alarm and automatic fire detection system installed within the building has been modified, upgraded and altered to suite the occupancy group at the time. The minimum category installed appears to conform to a minimum L4 type; (escape routes). Although limited coverage was found in some adjoining rooms and specific areas.

However, it is not possible to say with any degree of certainty what overall category of Fire Alarm & Automatic Detection is installed within all parts of this building. However, I am confident that the minimum level of Fire Alarm and Automatic Fire Detection installed is adequate for the risk within each area of the building. However, it is recommended in this Fire Risk Assessment that the Fire Alarm & Automatic Detection System be examined to ensure overall compliance with current BS 5839: Part 1: 2002 + A2 2008. Visual warning fire alarm devices are incorporated into a small number of the audible devices installed within a few areas of the building; (refurbished areas). The installed fire alarm & detection system is monitored by onsite 24hrs security provided by Estates Security Services.

Water supplies for fire fighting operations are taken from local authority ground hydrants installed under the public pavements; opposite the Grahams Hill Building, Richmond Street and Rottenrow. Hydrant indicator marker plates are required; (Local authority).

The principal entrance is served by 2 x 2 double leaf glazed and metal framed double swing opening doors. These are available to a person in the event of escaping from a fire. Most of the building occupants' access and egress the building using the final fire escape doors adjacent to the security supervisors' office. The North Portland Street exit is served by a single leaf outward opening final exit door; this door is fitted with a panic bar across its width and is not in general access use. The two central stairs both exit into separate ground level exit routes. The eastern ground floor lobby, comprises a lift lobby and exits past the security services office and fire panel onto Richmond Street.

A Dry Riser fire fighting installation is installed in the building serving the central stair enclosure. The outlet housings were non-conformant. However, these were generally suitably marked and were easily identifiable. The original hose reel installation has been removed. Although some signage for apparatus was still evident. Many of the original fire resisting door-sets were in a very poor state of repair.

It is anticipated that a major refurbishment will be carried out by Estates Services following an on-going feasibility study to alleviate many fire safety issues, some outlined above and within the Fire Risk Assessment and these form part of on-going discussions.

AVERAG	BE NUME	BER OF	STAFF ON PREMI	SES	A e d		SE NUM	BER OF O		DN PREMISES
Estimated number of	Day	Night	* Includes Security and		0.9.	Those Estima	at risk o ated nun	of Fire; hber of	Day	Night
employees at Work	500	< 20	Cleaners.			persor	IS		1500	< 20
Daytime Ave	rage for	2000)		Night ti	me aver	age for	< 20		
premises					premise	es	<u> </u>			
						• •		1.	0.1.4	
Others (Non	-	Variable	e			Consid	deration	Lone	& late wo	orking policies in
employees						3			ice.	
Occupancy	00:00	-06:00	06:00-12:00		12:00-18	3:00	18:0	0:00:00		Remarks
Density										
(24 hours)										
Sunday	< 20		< 20	< 2	20		< 20			
Monday	< 20		2000	20			< 150			
Wednesday	< 20		2000	20			< 150			
Thursday	< 20		2000	20	00		< 150			
Friday	< 20		2000	20	00		< 150			
Staurday	< 20		< 20	<	20		< 20			
Bank	< 20		< 20	< 2	20		< 20		Premise	es made lockfast
Holidays									at appro	oximately 18.30
									hrs eac	h weekday.
DEDENDENO				TLIN	DDEMIC			of in dividue	ala far aca	h alagaifigation)
DEPENDENC	T GLAS	SIFICAT	ION OF THOSE W		PREIMIS	ES (State	e number	of individua	als for eac	n classification)
HIGH: Individuals who are totally dependent on staff and may require the assistance of 2 or more staff members in a fire emergency.			MEDIUM: In will require staff mem fire emerge can, unain a longer t	idividua e assis ber to gency; ded, ey ime to	als who: stance or g respond a or kit the prem do so.	uidance f ppropriate nise but w	rom a ely in a /ill take	LOW: Indi and menta emergenc unaided.	viduals wh al capability y and exit t	o have the physical to respond to a fire he premise

N/A V	NumbersPEEPVariableprocedureapplicable		X	
-------	--	--	---	--

PERSONS /OCCUPIERS RESPONSIBLE FOR FIRE SAFETY PROVISIONS AND IN CONTROL OF PREMISES:~

Occupiers:

@ January 2011:~	
Catering Services	Careers Service
Central Teaching Pool	IT Services
Estates Services	Learning Services
Security Services	Music
Students Union	Safety Services (Occupational Health)
UCU	Student health service
Unison	Occupational Health
English Studies	Celtic Music Radio Ltd
Modern languages	Faculty of Humanities & Social Sciences
Mathematics & Statistics	Computer & Information Sciences
Hunter Centre for Entrepreneurship	

DATE OF ASSESSMENT	25 th Jan -11 th February 2011	DATE OF ASSESSMENT REVIEW (on a yearly basis or in the light of change)	Circa Feb. 2012
DATE OF ISSUE	14 th February 2011		

PART A – PROCEDURAL AND OPERATIONAL

	Air responses in Fart A must be evidenced by supporting records, procedures of other relevant		lentatio	<u>n.</u>
MEA	NS OF ESCAPE	YES	NO	N/A
1	Are all internal and external escape routes and stairs maintained in a safe condition?		X	
2	Are floor surfaces on escape routes kept free of slipping and tripping hazards?		X	
3	Are all internal and external escape routes checked regularly to ensure they are kept clear of obstructions and storage?		X	
4	Are regular checks made of the fabric condition of escape routes and passageways?		Х	
5	Are all escape routes well lit during the operational hours of the premises?		X	
6	Are all routes serviced by emergency escape route lighting?		Х	
7	Is the emergency escape route lighting system tested and maintained?	Х		
8	Are doors on escape routes and final exits in good condition and operating freely, closing without obstruction?		X	
9	Do doors within internal escape routes open in the direction of travel?		Х	
10	Are doors on escape routes and final exits operational without the use of a key, swipe card or key		X	
11	Are fire doors within escape routes and those from rooms onto protected escape routes fitted with suitable self-closing devices?	Х		
12	Are self-closing devices on doors maintained in good working order?		X	
13	Are automatic door release mechanisms on doors maintained in good working order?	Х	24	
14	Are external routes and stairs at a suitable safe distance clear of glazed areas / windows?		Х	
15	Do final exits lead to a place of safety?	Х		
15a	Is the place of safety clear of the building and away from traffic?		Х	
16	Is the assembly point(s) clearly identified, marked and away from the building.		Х	
16a	Is the assembly point clear of emergency vehicle access?		Х	
17	Are all doors, escape routes, exits and the direction of escape appropriately marked using clear legible signs with pictogram and supporting text?		X	
18	Are records of all the necessary checks, tests and maintenance detailed in this section available or held with the Estates Services Department?	Х		
FIRE	EVACUATION PROCEDURES	YES	NO	N/A
19	Is there a written, premises specific Emergency Fire Action Plan in place outlining the procedures to be followed?	Х		
20	Do these procedures take account of specific arrangements for individuals with mobility impairment or additional support needs?	Х		
20 20a	Do these procedures take account of specific arrangements for individuals with mobility impairment or additional support needs? Is an evacuation lift installed and available for use?	X X		
20 20a 20b	Do these procedures take account of specific arrangements for individuals with mobility impairment or additional support needs? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed?	X X X		
20 20a 20b When asses	Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children pu 4. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u	X X what rise remise se of I	sk lings es puildir	gs.
20 20a 20b When asses	Is an evacuation lift installed and available for use? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children pu 4. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at	X X what rise remise se of I X	sk lings es puildir	gs.
20 20a 20b When asses	Is an evacuation lift installed and available for use? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children pu 4. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions?	X X what ris n build remise se of I X X	sk lings es puildir	gs.
20 20a 20b When asses 21 22	Do these procedures take account of specific arrangements for individuals with mobility impairment of additional support needs? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children pr 4. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises?	X X what rise remise se of I X X	sk lings es puildir	gs.
20 20a 20b When asses 21 22 23	Is an evacuation lift installed and available for use? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation action notice (including simplified plan as necessary) displayed in rooms within sleeping accommodation?	X X what rise remise se of I X X	sk lings s puildir	gs.
20 20a 20b Wher asses 21 22 23 24	 Do these procedures take account of specific arrangements for individuals with mobility impairment of additional support needs? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? Te high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children provide the state of the safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at statiwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at statiwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at statiwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at statiwells on each floor of the premises? Is a fire evacuation procedures/action notices (including simplified plan where appropriate) displayed at statiwells on each floor of the premises? Is a fire evacuation procedures/action notices (including simplified plan where appropriate) displayed at porporriately in other areas e.g. within staff rooms and adjacent to manual fire alarm break glass call points? 	X X what rise remise se of I X X	sk lings es puildir	ngs. X
20 20a 20b Wher asses 21 22 23 24 25	Do these procedures take account of specific arrangements for individuals with mobility impairment of additional support needs? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children properties and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation procedures/action notices (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation procedures/action notices (including simplified plan where appropriate) displayed at stairwells on the act floor of the premises? Are fire evacuation procedures/action notices (including simplified plan where appropriate) displayed at appropriately in other areas e.g. within staff rooms and adjacent to manual fire alarm break glass call points? Are there sufficient numbers of designated members of staff (e.g. Fire Safety Co-ordinators and Fire Assistants) throughout the premises and during all operational times to assist and manage evacuation?	X X what rise n build remise se of I X X	sk lings ss ouildir	gs. X
20 20a 20b Wher asses 21 22 23 24 25 26	 Ib these procedures take account of specific arrangements for individuals with mobility impairment of additional support needs? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? Te high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at appropriately in other areas e.g. within staff rooms and adjacent to manual fire alarm break glass call points? Are there sufficient numbers of designated members of staff (e.g. Fire Safety Co-ordinators and Fire Assistants) throughout the premises and during all operational times to assist and manage evacuation? 	X X X what rise remise se of I X X X	sk lings s ouildir	ngs.
20 20a 20b Wher asses 21 22 23 24 25 26 26a	Is an evacuation lift installed and available for use? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? re high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for educational and day care for children pu 4. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stainwells on each floor of the premises? Is a fire evacuation notice (incl. simplified plan as necessary) displayed in rooms within sleeping accommodation? Are fire evacuation procedures/action notices (including simplified plan where appropriate) displayed appropriately in other areas e.g. within staff rooms and adjacent to manual fire alarm break glass call points? Are there sufficient numbers of designated members of staff (e.g. Fire Safety Co-ordinators and Fire Assistants) throughout the premises and during all operational times to assist and manage evacuation? Are fire evacuation drills carried out at least twice yearly? Are records kept of all drills carried out?	X X X what rise remise se of I X X X X X	sk lings ss buildir	gs.
20 20a 20b Wher asses 21 22 23 24 25 26 26a 26a 27	Do these procedures take account of specific arrangements for individuals with mobility impairment of additional support needs? Is an evacuation lift installed and available for use? Is there an disabled evacuation communications system installed? e high or medium dependency has been identified for individuals (see front page of assessment), ssment and subsequent arrangements have been established for evacuation? 1. Health & Safety Policy of the University of Strathclyde 2. Practical Fire Safety Guidance for the evacuation of disabled persons from 3. Practical Fire Safety Guidance for offices, shops and similar premises 5. BS 9999: Code of Practice for fire safety in the design, management and u Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at entrances and receptions? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at stairwells on each floor of the premises? Is a fire evacuation procedures/action notice (including simplified plan where appropriate) displayed at appropriately in other areas e.g. within staff rooms and adjacent to manual fire alarm break glass call points? Are fire evacuation procedures/action notices (including simplified plan where appropriate) displayed appropriately in other areas e.g. within staff rooms and adjacent to manual fire alarm break glass call points? Are there sufficient numbers of designated members of staff (e.g. Fire Safety Co-ordinators and Fire Assistants) throughout the premises and during all operational times to assist and manage evacuation? Are fire evacuation drills carried out at least twice yearly? Are records kept of all drills carried out? Has a specific person been assigned to liaise with the attending Fire and Rescue Officer in the event of a fire?	X X X what rise remise se of I X X X X X X X	sk lings ss ouildir	gs.

20	In addition to any established assembly / muster point(s) are there arrangements for short term shelter	X		
29	In the case of multiple assembly / muster points at the same premises, is there a suitable means of	X		
30	communication between each and the main point?	Λ		
FIRE	ALARM AND AUTOMATIC DETECTION SYSTEMS	YES	NO	N/A
31	Has a fire alarm system been installed?	X		ļ
32	Does the system include heat or smoke detection?	X		
33	Are all vulnerable areas within the premises covered by the detection system?		X	
34	Are all "break glass" points clearly visible, accessible and where necessary signed?	X		
35	Is the fire alarm system audible in all parts of the building?	X		
36	Is the audible alarm system supplemented by visual indication in noisy locations where the alarm cannot be heard?	X		
37	Are there provisions for individuals who, due to impairment or additional support need, cannot hear (or interpret) the alarm?		Х	
38	Is the system suitable for the type of premises in identifying specific rooms or zones on activation?	Х		
	Is the main fire alarm control panel (and any mimic panels) accessible and controls / read outs easily		X	
39	understood?			L
40	Is the fire alarm control/indicator panel checked on a daily basis?		X	
41	Is the fire alarm tested for function and audibility on a weekly basis during operational times / hours? (09.40hrs – Friday))	X		
42	Is the fire alarm system serviced and maintained monthly, quarterly and yearly as required?	X		
43	Are records of all the necessary checks, testing and maintenance detailed in this section available or held with the Estates Services Department?	X		
POR 44	TABLE FIRE EXTINGUISHERS AND FIXED SUPPRESSION SYSTEMS (e.g. sprinklers) Are suitable portable extinguishers provided (includes fire blankets), within the premises?	YES	NO	N/A
	Are portable extinguishers suitably positioned as to be readily available, accessible, and conspicuous	~	X	
45	and where necessary signed?		~	
46	Are portable extinguishers suitably installed, either wall mounted or on a floor stand?	X		
47	Are extinguishers checked at least monthly, to establish that they are in position and have not been tampered with or discharged?		X	
48	Are portable fire extinguishers maintained on a yearly basis and labelled as such?	X		
49	Where installed, are "deluge" systems (e.g. inert gas) in computer suites, are there specific operational arrangements for evacuation?			X
50	Where installed, are suppression systems (e.g. sprinklers) checked and maintained on a, weekly/monthly/quarterly/yearly basis as required?			X
51	Are records of all the necessary checks, testing and maintenance detailed in this section available or held with the Estates Services Department?	X		
FIRE	SAFETY TRAINING	YES	NO	N/A
52	Do all new staft (including those changing work location) receive fire safety awareness training including local procedures as part of their induction?	X		
53	Do all staff receive refresher information and instruction specifically for fire safety?		X	
	Are Fire Safety Co-ordinators and others who have responsibility to assist and manage evacuation)	X	~	
54	trained in accordance with the Occupational Health & Safety Policy incorporating Fire Safety?	~		
55	Have all Fire Safety Co-ordinators & Fire Assistants attended training within the last two years? (S17)		X	
56	Are records of all information, instruction and training available within the Premises? (S17)		Х	
GEN	ERAL FIRE PRECAUTIONS	YES	NO	N/A
57	Is a Fire Precautions Log Book provided for these premises?		X	L
58	Are individuals with responsibility for completing checks readily identified?	X		
59	Are all relevant sections of the Fire Precautions Log Book being completed accordingly?		X	
60	Is the University Policy on Smoking in and around University buildings enforced?		X	
60a	Are "NO SMOKING" signs displayed?		Х	
61	Where smoking is permitted in designated areas within residential premises, are there suitable formal arrangements and facilities in place?			X
62	is the workplace regularly inspected to ensure that it is in good order and free of accumulated rubbish?		X	
63	Are metal bins (without plastic bin liners) provided in areas with open public access?		X	
64	Are all rooms/areas with open public access inspected at the end of each working day?		X	
	Are quantities of combustible material on notice boards, displays etc managed to minimise the risk fire		X	
65	and spread?			
66	safe and proper manner?			X

	Is external storage of combustible materials or highly flammable substances secure, safe with regard		Х	
67	to wilful fire raising and at a safe distance from the premises?	v		
68	kept to a minimum?	X		
	Are the fire resistance Standards (BSEN) of all furnishings and fittings etc appropriate to the type and		Х	
69	use of the premises and are they labelled accordingly?			
70	Are the fire safety Standards (BSEN) considered when ordering replacements for furnishings, furniture	Х		
70	Where additional heaters are put into use, are they suitably secure and positioned as to minimise the		V	
71	hazard of ignition of combustible materials?		^	
72	Where vented tumble dryers are in use, are the lint filters cleaned after every operation?			Х
	Are air vents and extractors examined and regularly cleaned to ensure there is no build-up of		X	
72a	combustible dirt deposits?		~	
72	Within kitchens, are fat deposits removed regularly from ovens, ranges, fume hood extractors and	Х		
E E	CTRICAL EQUIPMENT AND SYSTEMS	YES	NO	N/A
	Is electrical equipment regarded as "portable appliances" subject to "PAT" testing and labelled		X	
74	showing the test (or test due) date. (circa Mar 2009 of items sampled)		~	
	Are fixed electrical systems and installations within the premises examined and where necessary	Х		
75	tested at specified appropriate intervals?		V	
10	Are electrical cables shed where damage will be minimised?		X	
77	is non-essential electrical equipment switched off when not in use and at the end of each working day?			X
	Is there a suitable written procedure in place to prevent faulty equipment being used whilst awaiting		Х	
78	repair e.g. labelled, quarantined, removal of plug etc?			
70	Are electrical cupboards and switch rooms suitably identified and secured with restricted access to		Х	
79	Where storage of certain specified materials is permitted within switch rooms, are they stored at least	Y		
80	1 metre away from switchgear, with clear access?	~		
	Where storage of certain specified materials is permitted in switch rooms within residential premises,			X
81	are distribution boards enclosed by a fire rated partition with clear access?	VEO	No	
ACI	As far as could be ascertained have all activities or processes, which may present a fire hazard, been	TES	NO	N/A
82	Risk Assessed (under Health & Safety legislation)?			^
	As far as could be ascertained. Where activities or processes generate levels of flammable or			X
83	explosive gas, liquid, tume, vapour or dust, are suitable control measures in place to reduce the fire			
	As far as could be ascertained. Are there monitoring or detection systems installed in the event of any			X
84	failure, release or spillage?			~
OE	As far as could be ascertained. Are physical controls, including isolation in place for containment in the			Х
86	Have written emergency procedures been established in the event of any failure release or spillage?			v
97	Are LPG or other gas cylinders used or stored in a safe and proper mapper?			^ V
07	Where processes involve the use of evidicing substances are they stored at used in a sofe and proper			X
88	manner?			X
MAN	IAGEMENT OF CONTRACTORS	YES	NO	N/A
	Are Contractors formally advised of the fire precautions and evacuation procedures for the premises	Х		
89	prior to starting work?			
90	detectors and for fire extinguishers being moved and fire doors being held open?	Х		
	Is hot work (e.g. burning, welding, roof felting) controlled under a permit to work system with the	X		
91	contractor also providing appropriate fire extinguishers?			
02	Where work requires the temporary isolation of the fire/detection alarm system, are alternative formal	Х		
92	Where work is liable to involve the removal of fire signs, notices etc. is the area checked to ensure		Y	
93	they have been reinstated?		~	
	Is the work area checked at the end of the working day and on completion of work, prior to the	Х		
94		VES	NO	NI/A
ЭПА	If you have direct control of the premises have you made arrangements for co-operation amongst all	159	NO	Y
95	occupiers and co-ordination of procedures and action?			^
	If you do not have direct control of the premises, has the lead occupier sought your co-operation and	Х		
96	provided you with information relating to fire safety matters?	VER	NO	NI/A
97				N/A
	Is there a fire fighting lift installed?	Y		
98	Is there a fire fighting lift installed?	X		
98 982	Is there a fire fighting stair installed?	X X	v	

Fire Risk Assessment 2010 Page 8 of 30

98b	Is there a smoke clearance system installed? X					
99	Is there	a fire fighting Dry Riser installed?	X			
100	Is there	a fire fighting Wet Riser installed?			Х	
101	Is there	a fire fighting lobby installed?	Х			
102	Is there	a fire fighting communications system installed?		Х		
103	Is there	a designated fire fighting vehicle appliance parking area?		X		
104	Is there	plans and/or drawings available for fire & rescue service use?	x			
105	 J5 Is there a Fire Control room available for fire & rescue service use? X 					
106	Is there	a sufficient supply of water for use by fire-fighters?	X			
		ADDITIONAL EXPLANATORY NOTES				
		Reference to fire hazard or management action in relation to the operation of the prem	nises.			
A	4.1	General storage, lockers and office furniture stored within the corridors & mea	ins of e	escape		
^	\mathbf{v}	stairways. (See photos 19-20a).			10.0	
P	1.∠	trip or fall hazard. (See photos 26 & 27)	cape n	lay cat	ise	
Δ	13	It was noted Security Services will report any serious obstructions and /or refu	ise acc	rumulat	tions	
,		However it was noted that corridors are used for staff & student lockers, siting		ce files	and	
		the storage of general items of furniture and discarded items. (See Photos 5,	20 & 2	4-27).		
A	٨.4	The condition of escape routes varied from floor to floor. it was noted that olde	er and	origina	l fire	
		doorsets were in a poor state of repair with excessive wall surface linings (No	tice bo	ards) tł	nat	
		did not meet benchmark standards. (See photos 34-35 & 21-25).				
Α.	.5-6	External lighting required around the rear of the Collins building to adequately	illumir	nate es	cape	
	\ o	route.		fr	/	
F	4.8	Original life doors were in a poor state of repair. Many had excessive gaps be		Trame . 5)	/	
Δ	<u>م</u>	Only where necessary doors due to occupant / storey capacities will doors b	o roqui	ired on	on in	
,	1.5	the direction of travel. However, inward opening doors found serving the large	e teach	ina roo	mon	
		the 14 th level; which had a potential seated occupant capacity in excess of 60	persor	ns.		
A	.10	Some internal doors fitted with electronic securing devices will fail to the safe	positio	n on th	e	
		operation of the fire warning system. Mechanical securing devices release on	lever a	actuatio	on.	
		It was noted that some doors did not appear to comply with BS 7273:part 4: 2	007, P	art 4:		
	10	"Actuation of release mechanisms for doors."				
A	.12	Several self-closing devices required to be adjusted to ensure door lears close	e over	onto th	е	
Δ	14	No fire resisting diazing separating Security Control offices from main escape	route	15.		
	15	All escape routes ultimately lead to a Place of Safety out-with the building	Toule.			
A.	15a	As there is no clearly designated and marked Assembly Points, many occupa	nts ten	d to		
		congregate adjacent to the entrance and exits of the building. Causing possib	le pede	estrian		
		/vehicle accidents and obstruction to fire-fighters accessing facilities.	•			
A	.16	Therefore:~				
		1. A "Fire Assembly Point" sign is required to be positioned at the design	ated a	rea, wh	ich is	
		located within Rottenrow Gardens opposite the main building entrance	.(see I	Photo n	nain	
		picture above).	ortical	ourfooo		
		2. All signage is to be afficed in a conspicuous location and to suitable ve approximately 1.75m from around level. The sign should bear the word	de "Fire		, mblv	
		Point" or as in accordance with the signage proposals outlined by Esta	ates Se	ervices.	The	
		sign should be in white lettering approximately 75mm in height on a lice	tht gree	en		
		background.	Ū			
A	.17	Additional escape signage to clearly indicate the external route to be followed	to the	assem	bly	
		point around the rear of the Collins building is required. Obsolete signs in use	throug	hout th	ie	
	10	building are to be removed and replaced with current compliant signage.(See	Photo	8 & 32	-24)	
A	.19	An Emergency Fire Action Plan (EFAP) has been compiled for the building. A	II staff	are to b)e	
A 20	0-20h	An evacuation lift for the disabled has been installed (No:107) (See plate 10)	unator) Thic /	5 (F3U aleo ac	Sj. te ac	
A.20	0-200	a fire fighting lift for fire-fighters. An " $FV/\Delta C$ " comme sytem is in place for disable	led eve	alou ac acuatio	ເວ dວ n	
		Evacuation chairs provided currently for specific areas of need identified in PF	EEP.	200010		
			•			
A 21	22 &	Partial compliance here: Fire Action Notices are to be provided and displayed	throuc	nhout th	1e	

24	haphazardly. These should be positioned in accordance with agreed Estates Services
4.05	guidelines.
A.25	Fire Safety Coordinators & Fire Safety Assistants have been appointed. Additional personnel maybe required due to the relocation of some staff as a result of on-going departmental
A 26	Currently carried out 6 monthly. A new electronic Fire Log book is in the process of being
A.20	compiled and maintained by Estates Services. Fire drill records currently kept by U.E.S.A
A 07	Complied and maintained by Estates Services. File drill records currently kept by 0.F.S.A.
A.21	Fire service vehicular access currently around approximately 50% of building. (Pichmond &
A.20	North Portland St's) Limited access to rear of main building due to restricted access from
	projecting shops on George Street and overall height of structure. Fire Service High reach
	Platform/Ladder access to approximately 8-9 th floor level
A.30	One assembly point. However, hand held radios in use by Security Services personnel, key
	personnel and Safety Services. Loudhailer also available.
A.31-43	A fire alarm and automatic fire detection system is installed within building. The fire alarm and
	automatic fire detection system has been modified, upgraded and altered to suite the occupancy
	group at the time. Fire detection within head of lift shaft enclosure. The detection is installed
	primarily within escape routes. Limited coverage within adjoining rooms. No visual inspection of
	panel carried out daily. All maintenance carried out by fire alarm engineers and onsite Estates
	Services. The main fire panel is located within the main lobby serving the Richmond Street
	entrance. No zone plan is available adjacent the main fire alarm panel. Limited visual warning
A 11-18 8	All portable equipment provided and serviced by Chubb. Some localised general storage was
51	found to be blocking immediate access to fire fighting equipment. There is no current
01	programme for monthly checking as recommended in BS 5306; part 3; 2000. It is recommended
	that a survey be carried out to ensure that the type, number and suitable location complies with
	the minimum standard of portable fire fighting equipment required as per BS 5306: Part 8: 2000.
	University online induction training carried out as new staff, arrive on site.
A.52 &	There is no formal annual training regime for staff. Five year refresher required as per Occ. H &
A.53	S Policy. It is recommended that all staff is given an annual; minimum 30 minute refresher by
	FSC. A record of those receiving tuition is to be kept by the department for inspection at any
	time when requested by an enforcing authority.
	FSC's & Assistants undergo fire safety training. Safety Services offer in nouse training.
A54-55 A 56	proactive
A.30	No building Fire Precautions Log Book is available. Currently all records are kept by Estates
A.57-59	Services. An electronic Fire Precautions Log book is currently being compiled by Estates
	Services.
	"No Smoking signs" with details of designated smoking areas and policy to be followed are to be
A.60a	provided internally within staff and common rooms. Externally a sign should be displayed at
	exits, indicating that No Smoking is allowed adjacent to the building entrance within a prescribed
	distance.
A CO8C4	No regular inspection regime in place (See Photos 24-27).
A.02&04	Cardboard boxes with bin liners in place and in use within building.
A.03 A 65	linings in the form of display and poster materials (See Photos 21-26)
A.05	Unsecured and haphazard storage of refuse & discarded furniture adjacent to lower escape
A.67	route exit outside the Collins building. External bin storage within the adjacent lane or loading
-	bay was apparent. No management of wheelie bins was evident. Any storage container is to be
	kept lock fast, except for access. Arrangements to be made to ensure swift and immediate uplift
	in order to safeguard escape route from act of wilful fire-raising. (See Photos 41, 42 & 44).
	No labelling available or apparent on sampled items of furniture.
A.69	Free standing floor mounted convection heaters were in use within isolated rooms of the
A.71	building, mainly in office environments. Those identified were located in areas clear of adjacent
	COMDUSTIDIES.
Δ 72-	The vest majority of portable electrical equipment sampled at the time of this assessment was
A 74	found to have been "PAT" tested (Mar'09)
	Extension leads were found hanging and passing through smoke door partition within 14 th level

A.76	corridor. (See Photo 9).
	No written procedure apparent in place for the reporting of defective or obsolete equipment.
A.78	All electrical switch rooms and plant rooms were identified. However these require to be kept
A.79	locked shut except for access. (See Photo14, 32 & 47).
	Arrangements to be made to ensure fire signage replaced.
A.93	A fire-fighting lift (No 107) is installed within central core. Structural fire protection was found to
A.97	be compromised due to forced air system feeding all levels within lift lobby. (See Photos 13 &
	17).
	A fire-fighting stair has been provided for this building. However this is not against outer wall.
A.98-98a	(See Photos 15-16).
	No smoke clearance / ventilation system has been installed either at the top of the stair well or
A.98b	by any means for open-able windows to allow limited ventilation of the stairway if deemed
	necessary.
	Dry Riser outlets have been installed within main central lift lobby/landings serving all levels.
A.99	(See photos 17, 18 & 18a).
	Fire fighting lobbies serving lift and stair enclosures are installed.
A.101	No dedicated communications system installed for use by fire-fighting teams.
A.102	No dedicated vehicle access. However, vehicle access and parking is provided by the adjoining
A.103	public highways of Richmond Street and North Portland Street. Limited high reach access to the
	building is provided via George Street, North Portland Street and Richmond Street.
	Detailed plans are available in electronic format from Estates Services (These are currently
A.104	being revised with regards to level of detail for specific trades including fire related issues).
A 106	water supplies are taken from the local town mains via ground hydrants under adjoining public
A.106	Pavements. Nearest available: Richmond Street, Montrose Street, George Street and North

INFC	FORMATION WHICH MAY ASSIST THE ASSESSMENT PROCESS e	.g. plans schematic	YES	NO	N/A
1	Has a previous Fire Risk Assessment been carried out for the premise	s?	Х		
2	Is there any information on any major adaptations or alterations that a issue of the previous FRA?	been carried out since the	X		
3	Is there any information on any construction, cabling work etc that ha	s been carried out which	X		
4	Is there up-to-date plans / schematics for the premises showing exit r call points extinguishers etc.? (general floorplans attached to the A	outes, fire doors, alarm		X	
5	Is there a Health and Safety File (under the Construction, Design and Regulations) available for the premises?	Management		X	
MAN	NAGEMENT OF CONTRACTORS		YES	NO	N/A
6	Are Contractors appropriately vetted, as per the policy for the Univers	ity, prior to being	Х		
7	Do Contractors make Method Statements and Risk Assessments avai	lable?	X		
8	Where work is liable to breach partition walls or other compartmentat to "making good" using appropriate fire stopping methods, within wo	ion, is specific reference ork order/specification?	X		
9	Where work is liable to breach partition walls or other compartmentat to ensure it has been reinstated or made good using appropriate fire s	ion, is the area checked stopping methods?		X	
BUIL	ILDING FABRIC		YES	NO	N/A
10	As far as could be ascertained is the general condition of the building required standard of fire resistance is maintained?	fabric such that the		X	
11	As far as could be ascertained the fire resistance of wall and partition to the required standard?	materials / coverings are		X	
12	As far as could be ascertained the compartment/fire separation walls and intact?	are in good condition		X	
13	As far as could be ascertained the floor materials / coverings are intac resistance to the required standard?	t and have a fire	X		
14	As far as could be ascertained the ceiling materials / coverings are int resistance to the required standard?	act and have a fire	X		
15	As far as could be ascertained the openings made between floors and installation of service cables and pipe work are protected to the requi	I rooms during the red standard in order to		X	
	restrict the spread of fire / smoke?				
16	As far as could be ascertained all structural voids (floor, ceiling, roof) required standard in order to restrict the spread of fire / smoke?	are protected to the		X	
17	As far as could be ascertained all lift shafts are protected to the require the spread of fire / smoke?	red standard to restrict	X		
18	As far as could be ascertained all ventilation ducts and openings are standard of damping/sealing to restrict the spread of fire/smoke?	protected to the required		X	
19	Where any building features such as atriums etc. may contribute to the suitable fire safety engineering control measures in place?	e spread of fire, are there		X *	
	Suitable me safety engineering control measures in place.		YES	NO	N/A
STR	RUCTURAL MEANS OF ESCAPE	he on the promises and	,	V	
20	the relative travel distances?	be on the premises and		X	
21	Are the maximum travel distances on routes to a protected zone / place required criteria in relation to the type of premises and directions of the	e of safety within the ravel?	X		
22	Are enclosed corridors, stairwells etc forming the exit routes construct resistance of at least half an hour; (short duration)?	cted to have a fire		X	
23	Do exposed surfaces or coverings within escape routes meet the star spread of flame (performance Class 0)?	idard for the surface		X	
24	Are all escape routes wide enough to allow safe and quick evacuation those using wheelchairs?	of occupant, including	X		
					1-
FIRE	LE DOORS Note: A door assembly consists of door frame; door	eaves; glazing; ironmon	gery; a	nd sea	IS.
door	or assemblies constructed?	nstalled?	Pre	35 &	
	BS1634-1:2008		B216)34-1:2	2008
			YES	NO	N/A
25	Is the fit of fire door leaves onto rebates and gaps such that fire / smo	ke resistance is		X	
26	Is the installation and function of intumescent strips, brushes or blad	es such that fire / smoke		X	
27	Is the installation and function of door furniture and vents such that fi maintained?	re / smoke resistance is		X	
28	Where door assemblies have been structurally altered or upgraded sin the required standard of protection against fire/smoke spread being n	nce initial installation, is net?		X	

FIRE	ALARM	AND AUTOMATIC DE	TECTION SYSTEMS				
To w Alarn	hich Stand n system i	dard (BS EN) is the nstalled?	Pre BS 5839 & BS 5839:pt 1	To which Standard (BS EN) is the Alarm system serviced and maintained?	B:	S 5839 002):pt 1
To w Deteo	hich Stand ction syste	dard (BS EN) is the em installed?	Pre BS 5839 & BS 5839:pt 1	To which Standard (BS EN) is the Detection system serviced and maintained?	B :2	S 5839 002):pt 1
			-	maintaineu	YES	NO	N/A
29	Are insta	llation and commission	ing certificates availabl	e for the Alarm and Detection systems?	Х		
30	Are the d rooms, la	letectors of the right typ aboratories, offices, res	e and appropriate to th earch areas and worksh	eir locations e.g. kitchens, teaching nops?		X	
31	If the fire supply?	-detection and warning	system is electrically p	owered, does it have a back-up power	X		
POR	TABLE F	IRE EXTINGUISHERS	. FIXED FIRE FIGHTII	NG AND FIXED SUPPRESSION SYST	EMS		
To w Extin	hich Stand guishers i	dard (BS EN) are the installed?	BS 5306:pt8	To which Standard (BS EN) are the Extinguishers serviced and maintained/	B	S 5306	6:pt3
To w Syste	To which Standard (BS EN) is the Fixed System installed? N/A To which Standard (BS EN) is the Fixed System serviced and maintained?			N/	Ά		
					YES	NO	N/A
32	Are the n	umber of extinguishers	adequate in relation to	the size of floor areas and travel	X		
32a	Are the lo	ocation of extinguishers s?	s suitable in relation to t	the size of floor areas and travel		X	
33	Are the ty within th	ypes of chosen extingu e premises?	shers suitable in relation	on to the nature of the fire hazards	X		
33a	Has the b	ouilding been fitted with	a Sprinkler system(s)?				X
33b	Is the sp	rinkler system been fitte	ed as a life safety system	n?			Х
ЕМЕ	PGENCV						
To w lighti	hich Stand	dard (BS EN) is the ed?	BS 5266:pt1:	To which Standard (BS EN) is the lighting serviced and maintained/	BS 5	266:p	t1:
					2005	,	
					YES	NO	N/A
34	ls appropuse of th	priate emergency lightir e premises?	ng installed within all re	levant areas in relation to the type and	YES	NO X	N/A
34 35	ls approp use of th Where er suitable	oriate emergency lightir e premises? mergency lighting is pro Declaration of Conform	ng installed within all re ovided, are Completion ity?	levant areas in relation to the type and Certificates available which includes a	YES X	NO X	N/A
34 35 36	Is approp use of th Where er suitable Where er an inder	oriate emergency lightin e premises? mergency lighting is pro Declaration of Conform emergency lighting is	ng installed within all re ovided, are Completion ity? provided for use whe	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there	YES X X	NO X	N/A
34 35 36 37	Is approp use of th Where er suitable Where er an indep Is the po	oriate emergency lightin e premises? mergency lighting is pro Declaration of Conform emergency lighting is pendent power sourc ower supply system to	ng installed within all re ovided, are Completion ity? provided for use whe e to that supplying th provided, maintained	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard?	YES X X X	NO X	N/A
34 35 36 37	Is approp use of th Where er suitable Where e an indep Is the po	oriate emergency lightin e premises? mergency lighting is pro Declaration of Conform emergency lighting is pendent power sourc ower supply system p	ng installed within all rel ovided, are Completion ity? provided for use whe e to that supplying th provided, maintained	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard?	YES X X X	NO X	N/A
34 35 36 37	Is approp use of th Where er suitable Where er an indep Is the por	oriate emergency lightin e premises? mergency lighting is pro Declaration of Conform emergency lighting is bendent power sourc ower supply system p erence to fire hazard or	ng installed within all re ovided, are Completion of ity? provided for use whe to that supplying th provided, maintained ADDITIONAL EXPL management action in	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the	YES X X X premis	NO X	N/A
34 35 36 37	Is approp use of th Where er suitable Where e an indep Is the po	priate emergency lightin e premises? mergency lighting is pro Declaration of Conform emergency lighting is pendent power sourc ower supply system p erence to fire hazard or Previous ERA carrie	ag installed within all rel ovided, are Completion ity? provided for use whe e to that supplying th provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there is normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006	YES X X X premis	NO X	N/A
34 35 36 37 B.1 B.2	Is approp use of th Where er suitable Where er an indep Is the po	priate emergency lightin e premises? mergency lighting is pro <u>Declaration of Conform</u> emergency lighting is pendent power source ower supply system p erence to fire hazard or Previous FRA carrie Continual upgrades to University Facult	ng installed within all relevided, are Completion of ity? provided for use whe to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to preview. Records be	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there <u>e normal lighting?</u> to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. D internal layout & structure. Change and by Estates services	YES X X X premis of occ	NO X es.	N/A
34 35 36 37 B.1 B.2 B.3	Is approp use of the Where ere an indeg Is the por	priate emergency lightin e premises? mergency lighting is pro <u>Declaration of Conform</u> emergency lighting is pendent power source ower supply system p erence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out o	ig installed within all relevided, are Completion of ity? provided for use whe to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to signification	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. o internal layout & structure. Change eld by Estates services. ant changes regarding alterations an	YES X X X premis of occ	NO X es.	N/A due
34 35 36 37 B.1 B.2 B.3 B.4	Is approp use of th Where er suitable Where e an inde Is the po	briate emergency lightin e premises? mergency lighting is pro Declaration of Conform emergency lighting is bendent power source ower supply system p ference to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Sources (Conoral	ag installed within all relevided, are Completion of ity? provided for use whe to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there is normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h	YES X X X premis of occur eld by	NO X es. upiers Estate	N/A due
34 35 36 37 B.1 B.2 B.3 B.4 B.5	Is approp use of the Where erection Where erection an indeg Is the portion Ref	priate emergency lighting e premises? mergency lighting is pro- Declaration of Conform emergency lighting is pendent power source ower supply system p erence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are avai Services. (General Information availab	ing installed within all relevided, are Completion of ity? provided for use where to that supplying the provided, maintained ADDITIONAL EXPL management action in and modifications to y review. Records here f date due to significa- ilable as to electrical floor plans attached to e in Estates archives	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently be	YES X X X premise of occu eld by eing u	NO X es. upiers upiers. Estate pdated	N/A due es).
34 35 36 37 8.1 8.2 8.3 8.4 8.5 8.6-5	Is approp use of the Where erection Where erection an indeg Is the portion Ref	briate emergency lightin e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is <u>bendent power source</u> ower supply system p derence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availab Vetting programme Managers	ag installed within all relevided, are Completion of ity? provided for use whe to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to e in Estates archives in place and contract	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently b s. tors are monitored by Estates Service	YES X X X premis of occur eld by eing up ces pro	NO X es. upiers Estate pdated	N/A due es).
34 35 36 37 B.1 B.2 B.3 B.4 B.5 B.6-5 B.10	ls approp use of th Where er suitable Where e an inde Is the po Ref	briate emergency lighting e premises? mergency lighting is pro- Declaration of Conform emergency lighting is bendent power source ower supply system pro- ower supply system pro- ference to fire hazard on Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availabl Vetting programme Managers. The formation of ve	ng installed within all relevided, are Completion of ity? provided for use whe e to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to e in Estates archives in place and contract	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently be s. tors are monitored by Estates Services.	YES X X X premise of occu eld occu eld by eing u eing u ces pro-	NO X es. upiers upiers. Estate pdated	N/A due es).
34 35 36 37 B .1 B .2 B .3 B .4 B .5 B .6-5 B .10	Is approp use of the Where erections Where erections an indeg Is the post Ref	briate emergency lighting e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is <u>bendent power source</u> ower supply system p derence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availab Vetting programme Managers. The formation of ve potential to cause s	ag installed within all relevided, are Completion of ity? provided for use whe e to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached f e in Estates archives in place and contract rtical ventilation shaf evere smoke-logging	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently b s. tors are monitored by Estates Service ts within stairs serving the upper leve g of the corridors and means of esca	YES X X X yremis of occur eld by eing up ces pro- els hav pe ser	NO X es. upiers Estate pdated oject ve the ving the	N/A due es).
34 35 36 37 8.1 8.2 8.3 8.4 8.5 8.6-5 8.10	ls approp use of th Where er suitable Where e an indep Is the po Ref	briate emergency lighting e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is <u>bendent power source</u> ower supply system pro- ower supply system pro- ower supply system pro- erence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availabl Vetting programme Managers. The formation of ve potential to cause s areas from a relative	ag installed within all relevere smoke-logging in by the states archives in place and contract	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently be s. tors are monitored by Estates Services ts within stairs serving the upper level g of the corridors and means of escal wer level. The topmost openings hav	YES X X X yremis of occu eld by eing u ces pro- els hav pe ser e beer	NO X es. upiers upiers. Estate pdated oject ve the ving the n cappe	N/A due es).
34 35 36 37 8.1 8.2 8.3 8.4 8.5 8.6-5 8.10	Is approp use of the Where erection Where erection an indeg Is the portion Ref	briate emergency lighting e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is <u>bendent power source</u> ower supply system p derence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availab Vetting programme Managers. The formation of ve potential to cause s areas from a relativ over. The shaft ope	ag installed within all relevided, are Completion of ity? provided for use whe e to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to e in Estates archives in place and contract rtical ventilation shaff evere smoke-logging ely small fire on a low nings /grills require to ad close fitting to the	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently be s. tors are monitored by Estates Service ts within stairs serving the upper leve g of the corridors and means of esca wer level. The topmost openings hav o be in-filled with imperforate fire res	YES X X X x premis of occu ad occu eld by eing u ces pro- els hav pe ser e beer isting [NO X es. upiers Estate pdated oject ve the ving the n cappe panels.	N/A due es).
34 35 36 37 8.1 8.2 8.3 8.4 8.5 8.6-5 8.10	ls approp use of th Where er suitable Where e an inde Is the po Ref	briate emergency lighting e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is <u>bendent power source</u> ower supply system p erence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availabl Vetting programme Managers. The formation of ve potential to cause s areas from a relativ over. The shaft ope Made and maintain also comment on F	ag installed within all relevanded, are Completion of ity? provided for use whe e to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to e in Estates archives in place and contract rtical ventilation shaff evere smoke-logging ely small fire on a low nings /grills require to ed close fitting to the pre-fighting ventilation	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there is normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently be s. tors are monitored by Estates Service ts within stairs serving the upper level g of the corridors and means of escal wer level. The topmost openings hav o be in-filled with imperforate fire res existing surrounds. (See photos 13, p A 98b)	YES X X X premis of occu eld by eing u ces pro- els hav pe ser e beer isting 14,15	NO X x es. upiers upiers. Estate pdated oject ve the ving the n cappe panels. &16). (N/A due es). ese ed See
34 35 36 37 8.1 8.2 8.3 8.4 8.5 8.6-5 8.10 8.11	Is approp use of th Where er suitable Where er an inde Is the por Ref	briate emergency lighting e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is bendent power source ower supply system p derence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information availabl Vetting programme Managers. The formation of ve potential to cause s areas from a relativ over. The shaft ope Made and maintain also comment on F Poor and extensive	ag installed within all relevanded, are Completion of ity? provided for use whe e to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to e in Estates archives in place and contract rtical ventilation shaff evere smoke-logging ely small fire on a low nings /grills require to ed close fitting to the ire-fighting ventilation surface spread of fla	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there e normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. b internal layout & structure. Change eld by Estates services. ant changes regarding alterations an , fire and fabric matters. These are h for reference only - plans currently be s. tors are monitored by Estates Service ts within stairs serving the upper leve g of the corridors and means of esca wer level. The topmost openings hav o be in-filled with imperforate fire res existing surrounds. (See photos 13, n A.98b) ame characteristics of wall notice boa	YES X X X x yremis of occu eld by eing u eing u ces pro- els hav pe ser e beer isting 1 14,15 ards ar	NO X x es. upiers Estate pdated oject ve the ving the n cappe panels. &16). (N/A due es). ese ed See er
34 35 36 37 8.1 8.2 8.3 8.4 8.5 8.6-5 8.10 8.11	ls approp use of th Where er suitable Where e an inde Is the po Ref	briate emergency lighting e premises? mergency lighting is pro- <u>Declaration of Conform</u> emergency lighting is <u>bendent power source</u> ower supply system p derence to fire hazard or Previous FRA carrie Continual upgrades to University Facult Previous FRA out of Floor-plans are ava Services. (General Information available Vetting programme Managers. The formation of ver potential to cause s areas from a relative over. The shaft ope Made and maintain also comment on F Poor and extensive combustible paper	ag installed within all relevited, are Completion of ity? provided for use whe e to that supplying the provided, maintained ADDITIONAL EXPL management action in ed out on the 28 th Ap and modifications to y review. Records he f date due to significa- ilable as to electrical floor plans attached to e in Estates archives in place and contract rtical ventilation shaff evere smoke-logging ely small fire on a low nings /grills require to ed close fitting to the re-fighting ventilation surface spread of fla- flyers / posters. (See	levant areas in relation to the type and Certificates available which includes a en the normal lighting fails is there is normal lighting? to the necessary standard? LANATORY NOTES relation to the fabric and structure of the ril 2006. De internal layout & structure. Change end by Estates services. ant changes regarding alterations and for reference only - plans currently be s. tors are monitored by Estates Service ts within stairs serving the upper level g of the corridors and means of escal wer level. The topmost openings hav o be in-filled with imperforate fire res existing surrounds. (See photos 13, n A.98b) ame characteristics of wall notice boa Photos 21-26).	YES X X X yremis of occu eld by eing u ces pro- els hav pe ser e beer isting 14,15 ards ar	NO X x es. cupiers upiers. Estate pdated oject ve the ving the n cappe panels. &16). (N/A due es). ese ed See er

16	corrido	ors/ levels. (See Photos 14, 18 & 18a).
B.18	The ve	entilation system appeared to be in a poor state of repair. No evidence of fire dampers
	was e	vident. A check is to be made to ensure that fire dampers are installed at locations where
	vents	pass through fire resisting walls, floors and ceilings, (See 13 & 14).
B.19	The ve	ertical shafts/ grills within both stairs appear to serve no design purpose. (See comment
	for A C	08a & B 10). Therefore the openings should be separated, if deemed unnecessary from
	the es	cane stairs by fire resisting construction of short duration
B 20-21	Some	lecture and computer rooms require 2 independent escape routes due to numbers
0.20 21	Romo	dial work is on-going for the building to ease occupant density on existing stairs and to
	roduce	and work is on-going for the building to case occupant density on existing stans and to
B 22	Evictin	a stair anglesures; including fire resisting deerests, have insufficient fire resistance.
D.22	duratio	ig stall enclosures, including me resisting doorsets, have insumclent me resistance
		in to meet at least 50 mins, (short duration) to ensure sale evacuation. This is due to
		(See Destee 24.8.25)
D 00	Dianta	(See Photos 54 & 55).
В.23	Plaste	r wail linishes found throughout. However, large areas of compustible wail hangings /
D 04	poster	s in situ. (See photos $21 - 24$).
B.24	I he ex	kisting stair widths serving all levels on the upper levels are sufficient and reasonable for
	the ma	aximum number of occupants imposed by the University at any one time. Congestion has
	been r	eported from 9 th level. Internal corridors of sufficient width for wheelchair users. Disabled
	persor	ns require assisted evacuation; via use of evacuation chair to safely negotiate stairs.
D 0 D 00	(See F	Photos 10, 10a & 52).
B.25-28	New fi	re doors were found to be in good order and fitted with intumescent strips and brushes.
	The ge	eneral standard of all other fire doors was poor. It was noted that there is poor fire / non-
	exister	nt smoke seal separation between the leaves of the double swing older style fire doors;
	(See F	Photo 34 & 35).
B.29	Estate	s Services hold all documentation in archives pertaining to all installations and
5.00	comm	issioning certificates.
B.30	The fir	e detection system and the devices installed within the building were found to be
	approp	priate for their respective locations and were of a minimum L4 type (escape routes).
	Althou	igh some devices are installed within adjoining areas as a result of subsequent
	refurb	ishment. It is recommended that the Automatic Fire Detection & Fire Alarm be examined
5	to ens	ure compliance with BS 5839: Part 1: 2002 +A2 2008.
B.32,32a &	Adequ	late portable fire fighting equipment is provided within the building. However it is not
33	sited u	iniformly throughout the building. Some local signage is required. The type, number and
	locatio	on of portable fire fighting extinguishers should be made to comply with the
	recom	mendations of BS 5306:Part 8: 2000. (See Photo 8, 22, 23 & 50).
B.33a	No spi	rinkler system is installed within building. There is no requirement under current building
	standa	ards or codes of practise. (Feasibility study as to need for sprinkler within the lower car
	parkin	g areas of the building is to be carried out by Estates).
B.34	Emerg	pency lighting is installed within the building. It should be extended to adequately
	illumin	ate the external escape route around the Collins building. It is recommended that the
	Emerg	pency lighting be examined to ensure compliance with BS 5266: Part 1:2005.
B.35	Estate	es Services hold all documentation in archives pertaining to all installations and
	comm	issioning certificates.
B.36 & 37	Emerg	pency Lighting supplied from central battery system. Servicing carried out by service
	contra	ctors and Estates Services personnel.
		FIRE RISK RATING
		LIKELIHOOD OF FIRE OCCURRING
HIGHLY UNLI	KELY	Low likelihood of fire as a result of negligible potential sources of ignition within the premises.

UNLIKELY	,	Normal fire hazard (e.g. potential ignition sources) for this type of premises and occupancy, with fire hazards generally subject to proper and adequate control.				
LIKELY		Lack of adequate control applied to one or more significant fire hazard and as such would significantly increase the likelihood of fire to certain or near certain.				
Taking into acc likelihood of fi	count th re is:	ne fore	egoing information and fir	ndings at the	time of assess	ment, it is considered that the
HIGHL	Y UNLIK	ELY		UNLIKELY	x	LIKELY
			POTENTIAL CON	ISEQUENCE	S OF FIRE	
SLIGHT HAR	3HT HARM Outbreak of fire is unlikely to result in injury of any occupant of the premises.					
MODERATE H	ARM	Outbr	reak of fire could result in	injury or sig	nificant propert	y damage.
EXTREME HA	RM	Outbr premi	reak of fire could result in ises.	serious inju	ry or death of or	ne or more occupants of the
Taking into acc potential conse	count th equence	ne fore es of f	egoing information and fir fire could result in:	ndings at the	time of assessi	ment, it is considered that the
SL	IGHT H	ARM	MODE	RATE HARM	X	EXTREME HARM
			PC	TENTIAL CO	ONSEQUENCES	OF FIRE
LIKELIHOOD	OF FIF	RE	SLIGHT HARM	мо	DERATE HARM	EXTREME HARM
HIGHLY UN	ILIKELY		TRIVIAL RISK	TOL	ERABLE RISK	MODERATE RISK
UNLIKI	ELY		TOLERABLE RISK	MO	DERATE RISK	SUBSTANTIAL RISK
LIKEL	LY		MODERATE RISK	SUBS	STANTIAL RISK	I INTOLERABLE RISK
Applying the a	bove ris	sk rati	ng matrix, the risk of life f	rom fire with	nin the named p	remises is:
TRIVIAL	ТО	LERA	BLE MODERAT	= x	SUBSTANTIAL	INTOLERABLE
			BASIS OF AC	TION TO BE	TAKEN	
TRIVIAL	No act	tion re	auired			
TOLERABLE	No ma	ajor ad	ditional controls required of	her than mair	ntaining existing of minor or limited	control measures. However,
MODERATE	It is es	sentia	I that efforts are made to re	duce the risk	. Risk reduction	measures should be
MODEINATE	Where	e mode ish pre	erate risk is associated with ecisely the likelihood of harn	extreme harr n as a basis o	n, further assess of determining the	ment should be carried out to e priority for improved control
SUBSTANTIAL	Genei	les.				
	Consid		e resources may have to be		reduce the risk.	
INTOLERABLE	Premis reduce	ses (oı əd.	r specifically identified area	of building) s	hould be vacated	or not occupied until the risk is
	Copy to	be for	FIRE SAFE1 warded to the designated persor	TY ACTION	PLAN or the implementatio	n of Action Plan(s)
ACTION PLAN PRIORITY LISTING						

FAP 1	Immediate corrective action must be taken by the Manager in charge of the premises to be completed before the end of the day of the assessment visit .			
FAP 2	Where corrective action is out-with the authority or control of the Head of Department or Manager in charge of the premises. The designated named person within the University who is responsible for progressing the Fire Safety Action Plan must take the necessary corrective action either immediately or within the specified time outlined as part of the assessment report, as a target date for completion. Progress towards that date should be monitored. Where action cannot be completed within the prescribed period, a formal schedule of work including time scales must be established. The Head of Department or Manager in charge of the premises must however take short term preventative measures in lieu of the completed corrective action.			
FAP 3	Where corrective action can be taken in due course because of the comparatively low contributory risk presented. However, where action can be taken which involves simple measures or minimal resources then the appropriate action should be taken by either the Head of Department or Manager in charge of the premises.			
Copy to b	FIRE SAFETY ACTION PLAN Copy to be forwarded to the designated person responsible for the implementation of Action Plan(s)			

Question No.	Action Required	Action Plan Priority Listing	To Be Actioned By	Target Date For Completion
A.1-2	All combustible refuse materials, office furniture and storage are to be removed from all means of escape corridors and other protected routes. Thereafter all such areas are to be kept clear and free of storage in order to prevent injury to persons escaping from fire (See Photos24-27 41-	FAP 2	Estates Services & Department Heads	1 st July 2011
A.3	44) Regular checks are to be made to ensure that all escape routes and corridors are inspected and kept free and clear of	FAP 2	Estates Services & Department Heads	1 st July 2011
A.4	obstructions and combustible storage. Escape routes are to be checked on a regular basis to ensure all benchmark	FAP 2	Estates Services	1 st July 2011
A.5	standards are met. The emergency lighting should be examined to ensure that it covers all internal and external escape routes from	FAP 2	Estates Services	1 st July 2011
A.8	the building. The original fire door sets serving stair enclosures were found to be in poor condition. All such doors require to be made to have a fire resistance of at least 60 mins. and be maintained self-closing and close fitting onto the rebates. Intumescent seals and cold smoke brushes are to be fitted	FAP 2	Estates Services	1 st July 2011
A.9	and thereafter maintained in good order.(Photos 34 & 35). Exit doors serving lecture and computer rooms having an occupant capacity of more than 60 should be made to open in the direction of travel.	FAP 2	Estates Services	Ongoing programme

Question	Action Required	Action Plan	То Ве	Target Date For
No.		Priority Listing	Actioned By	Completion

A.10	All doors fitted with security devices,	FAP 2	Estates Services	Ongoing
	electro-magnetic or mechanical devices.			programme
	Should be made to unlock on the actuation			
	of a panic bar or on the fire and detection			
Δ 12	Self-closing devices particularly on older	FAP 2	Estates Services	Ongoing
7.12	doors, require to be adjusted to ensure that	174 2		programme
	door will close over from all angles of			1 3 5
A.15, 15a	swing.	FAP 2	Estates Services	Ongoing
& 16	The Fire Assembly points at all stipulated			programme
	locations are to be clearly marked with a			
	sign that is conspicuous and legible to all persons leaving the building. The sign			
	should bear the words "Fire Assembly			
	Point" or as in accordance with the signage			
	proposals outlined by Estates Services.			
	The sign should be in white lettering			
	approximately 75mm in height on a light			
	building			
	specific. All signage is to be affixed in a			
	conspicuous location and to suitable			
	vertical surface, approximately 1.75m from			
	ground level. Additional escape signage is			
	escape route to be followed in the event of			
A.17	fire to the place of safety from the	FAP 2	Estates Services	Ongoing
	Richmond Street exit.			programme
	"Push Bar to Open" signs required on all			
	doors fitted with a push bar mechanism.			
	(Photos 8, 28-31 & 34) Overall signage is			
A.19	currently being reviewed by Estates	FAP 2	Estates Services &	1 st July 2011
	Services.		Department Heads	-
	All staff are to be made aware of the			
A 21 22 8	contents of the Emergency Fire Action Plan		Entaton Sorvinon	Ongoing
A.21,22 &	(EFAP) for the building. A copy will be issued to all Fire safety Co-ordinators	FAP 2	Estates Services	programme
21	Fire Action Notices are displayed within the			programmo
	building to clearly outline the procedure to			
	follow in the event of fire. However, these			ist i i ooiii
A.25	are to be positioned in accordance with the	FAP 2	Department Heads	1 ^{or} July 2011
	Heads of Departments and line managers			
	should consider that additional Fire Safety			
	Co-ordinators & Fire Safety Assistants may			
	require to be appointed and trained due to			ist i i ooiii
A.31-40	the relocation of staff as a result of on-	FAP 2	Estates Services	1 st July 2011
α Β 30	going departmental changes within the			
D .00	The fire alarm & automatic fire detection			
	system installed throughout the building			
	should be examined to ensure compliance			
	with BS 5839: Pt 1:2002;+A2 2008 and if			
	hecessary the automatic detection should be extended to cover all areas as per the			
	recommendations of BS 5839:Pt 1.			
	The illuminated warning sign "DO NOT			et
	ENTER-FIRE ALARM" should be removed	FAP 2	Estates Services	1 ^{ະເ} July 2011
A.45	rrom the music directors' office. I o avoid			
	Any storage found to be blocking			
	immediate access to fire fighting equipment			
	on any of the escape routes, is to be			
	removed to allow			
Fire Risk A	i un-nindered access to all Extinguishing seesing et all 2010 Page 18 of 30			

Question No.	Action Required	Action Plan Priority Listing	To Be Actioned By	Target Date For Completion
A.47	All portable FFE is to be checked monthly as recommended in BS 5306: part 3: 2000. Therefore a programme of inspection is to be drawn up to ensure compliance.	FAP 2	Estates Services	1 st July 2011
A.52 & 53	After initial Induction training the ongoing training is carried out by The Dept. Safety Convenor and/or Fire Safety Co-ordinator.	FAP 2	Estates Services	1 st July 2011
A.54 – 56	All training to be reviewed and if deemed necessary selected personnel will be required to attend a FSC or Practical Fire Fighting course to ensure an adequate number of staff on duty.	FAP 2	Estates Services & Department Heads	1 st July 2011
A.57 & 59	Estates hold records of maintenance etc. Means of accessing records by all under discussion.	FAP 2	Estates Services	1 st July 2011
A.60-60a	"No Smoking Signs" are to be provided and positioned within the loading bay / service yard and externally at all exits.(See Photos 40 & 43). The sign should have a red background and bear the words "No Smoking", in white lettering and be of a height of minimum 25mm.	FAP 2	Estates Services	1 st July 2011
A.62-63	Cardboard bins should not be used within the University. All waste receptacles are to be of metal construction. Care required with regards to siting and location.	FAP 2	Estates Services	1 st July 2011
A.64 A.65	No formal inspection regime in place. Excessive use of noticeboards on majority of corridors serving the means of escape. (See Photos 21-24).	FAP 2 FAP 2	Estates Services Estates Services	1 st July 2011 1 st July 2011
A.67	All external refuse containers and areas where there is storage of combustible materials are to be secured against casual	FAP 2 FAP 2	Estates Services Estates Services	1 st July 2011 1 st July 2011
A.68	entry to avoid the possibility of wilful fire- raising. (Adjacent Collins)(Photos 41-44). Storage of stationery within escape routes	FAP 2	Department Heads	1 st July 2011
A.69	No evidence was found of compliance or labelling on furniture sampled.	FAP 2	Estates Services	1 st July 2011
A.71	All portable heaters are to be located away from combustible materials and secured against a wall to prevent obstruction.	FAP 2	Department Heads	1 st July 2011
A.72a	The ventilation ducts and grills are to be examined and thereafter maintained to prevent rapid fire spread.	FAP 2	Estates Services	1 st July 2011
A.74	All portable electrical apparatus is to be tested as and when required under current Regulations.	FAP 2	Estates Services	For discussion
A.76	All extension leads are to be used in in accordance with manufacturers' instructions. The cabling passing through he smoke corridor wall is to be removed.	FAP 2	Estates Services	1 st July 2011
A.78	No apparent procedure. Depends on degree of control by local management.	FAP 2	Estates Services	1 st July 2011
A.79	All Electrical switch-rooms are to be kept locked shut except for access.(Photo 14 & 47)	FAP 2	Estates Services	1 st July 2011
A98b	A smoke ventilation facility or opening vent at the head of the stair should be provided for use by fire-fighters. (Utilisation of vertical shafts maybe feasible with opening at upper levels)	FAP 2	Estates Services & Department Heads	For discussion

Question	Action Derwined			
No	Action Required	Priority Listing	To Be	Target Date For
A 00	The ovicting DP is to be eveninged to		Actioned By	
A.33	ensure that it complies with RS 5306. Part 1		LSIGIES SEIVICES	
A.102	Due to the complexity and overall floor area	FAP 2	Estates Services	For discussion
-	of the building, a communications system			

B.22	and flame within the stairs. (See 98b above) The existing original fire resisting doorsets found throughout the building should be upgraded or replaced with fire resisting doorsets meeting the criteria of BS 1634- 1/2008. Corridor within the building require	FAP 2	Estates Services	For discussion
	and flame within the stairs. (See 98b above)			
	enclosures are to be fully enclosed and made imperforate to the stair enclosure in order to prevent the rapid spread of smoke			
B.19	risers, ducts and cabling routes passing through fire rated walls and partitions require to be suitably fire stopped to prevent the passage of heat and smoke in the event of a fire. The vertical shafts within both stair	FAP 2	Estates Services	For discussion
B.10-12 & 15- 16	Photos 14 & 51). A small fire could cause severe smoke logging within stairs and corridors. See B.9 above & (See Photos 14 & 51) All service	FAP 2	Estates Services	1 st July 2011
B.9	Follow up checks to be made to ensure the satisfactory infilling of openings made for services, in fire rated walls partitions. (See	FAP 2	Estates Services	1 st July 2011
A.106	the recommendations of BS 9999. All external Fire Hydrants are to be suitably marked with an indicator plate.	FAP 2	Estates Services/ local authority	For discussion
	facilities, which is located on the ground floor. The present facilities are extremely vulnerable to fire and arson from even a small outbreak. To ensure business continuity during a fire situation. The control room should be enclosed within a fire resisting enclosure of at least 2hr and meet			
	contains all security cameras, fire alarm links, communications and ancillary equipment for the whole of the campus and beyond within the designated Control Room			
A.105	Estates. However, a copy should be kept within the office adjacent to the fire panel for use by fire service in the event of an emergency. A fire control room is not required for this	FAP 3	Estates Services	For Discussion
A.104	considered. Up to date floor-plans are available from	FAP 2	Estates Services	For discussion

B.25-28	Existing single / double leaf fire doors are to be fitted (where feasible) with intumescent strips and brushes in order to reduce the possibility of cold smoke and fire passing around and through the door frame and to be made and maintained self-closing and close fitting onto their frame / rebates. (See Photo 35)	FAP 2	Estates Services	1 st July 2011
B.30	Fire alarm & detection to be examined to ensure that it complies with BS 5839:Pt1 2002	FAP 3	Estates Services	For discussion
B.32	It is recommended that a survey be carried out to ensure that the type, number and suitable location complies with the minimum standard of portable fire fighting	FAP 2	Estates Services	For discussion
B.34	minimum standard of portable fire fighting equipment required as per BS 5306: Part 8: 2000. The existing Emergency Lighting should be examined and if necessary be extended to adequately illuminate all stairs and passageways both internally and externally in the event of fire.	FAP 2	Estates Services	1 st July 2011

Appendix A: Supporting Photographs:~

(N.C. Non-Compliant) (D. Description only).



(D). The rear escape route serving the 3 levels down to & around the Collins Building.









(N.C.)In-appropriate use of electrical extension leads.



(D) Evacuation chair & evacuation lift facilities



(D) Evacuation Communications.







(D)2 x Vertical air vents/ shafts 1 x within each main stair.



12



13



N.C.)Dry Riser (N.C)(18-18a) Poor fire stopping (N.C.)Escape routes and corridors used as an extension outlet boxes to adjoining voids & floors. non -compliant.



Fire Risk Assessment 2010 Page 23 of 30





of workrooms. To be found on most levels.



(N.C.)(21-23a) Poor surface spread of flame properties found on a large proportion of escape routes. Due mainly to poor management of noticeboards and all vertical surfaces, including doors.





(N.C.) Obsolete H/R signage







(N.C.)(24-27)Poor housekeeping was found in escape routes. Discarded office items and refuse were found during several visits on different dates to the building.



(N.C.)(28-31& 34) Obsolete fire signage was evident and in use throughout the building on most levels.





(N.C.)(32-33) Obsolete reference made to the location of the fire alarm panel.



(N.C.)(34-35 Excessive gaps on Fire doors. -old type.



(D)(37-39) New style fire door sets within refurbished areas. (D) Final exit and control





(N.C.) External open bin storage on escape routes from building and adjoining building. Poor signage.



(D) External Dry riser inlet on Fire Exit ramp.

49





(N.C.)(49-50) Evidence of Door wedging throughout.

(D) plant room







(N.C.) Poorly maintained Fire door self closers.



(D) Evacuation chairs available for use.

<u>Appendix B:</u> Floorplans for general reference are only to illustrate main internal layout and features: Not to scale in relation to following plans.





Fire Risk Assessment 2010 Page 26 of 30

	University of Strathclyde
Estates Management: CPT Modern Languages Estates Management	UNIVERSITY ESTATES MANAGEMENT John Anderson Campus 161 St. James Road Gjasgov G ANT Tel: 014-1552-4400 Fisc: 014-1552-4400 Fisc: 014-1552-4197 Tel: 014-1552-41
evel 5	EÅdn+rEstansePkoplansjøjøkA+2,T45.dog

Level 8

• • • • • • • • • • • • • • • • • • •		University of Strath	of aclyde
Image: specific transmission of the specific transmission of transmison of transmission of transmission of transmission of tra	Companie en Hormader Salacia	UNIVERSITY E John A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	STATES MANACEMENT offerion Carpus 83 Sumes Road spore 64 ONT 144-553-4157 97 Sale 97 Sale 97 Sale 97 Sale
Drawing No Bilding Conte Toming Time Toming Time Time Toming Time		F Project No	
Stating The Second S		Urawing No Building Code LT	
Barting Alg. Trialing Data Trialing Trialing		training the Foot Layout Level 11 Uningsome Tro John Anderson	ver Campus
L&M Survey Sengles Tip Top Exdentification@Reoptims/pip/AP4.T-11.dog		Scole A1 1200 A3 Drawn By	Date 17/03/08 Checked By
KAdmiEstateifkopterijejekAP2T41.dug		L&M Survey Sends	85
		K/Adminic statesin	corpansiatie v+P+CT+11.0vg

Fire Risk Assessment 2010 Page 32 of 30